## SOW CHANGE PROPOSAL

SOW-02-832-1-09999A-2/4, Change 2

7 August 2001

STATEMENT OF WORK (SOW)
For the
Inspection and Repair Only As Necessary (IROAN)
Of the
Light Armored Vehicle (LAV-MEWSS)
NSN 5865-01-236-4235
SOW-02-832-1-09999-2/4, Change 2

## Add new paragraph:

3.3.2.9

## To read:

3.3.2.9 Brake drums shall not exceed .036 inches (.912mm) above the standard measurement as outlined in TM 08594A 34/9A Paragraph 13-3. Those drums exceeding .036 (.912mm) must be replaced.

If approved, does this or schedule?	proposed change have the potential t	to have an impact on the cost
* Yes No	(Place an X in the appropriate	e block)
Maintenance Director	ne potential to impact cost or schedule rate (MD) and an impact statement protential to impact cost or schedule management.	ovided to LCMC. Changes
Change Submitted by	: 5577 Par /2 ) (1	Name) 24 <u>441</u> Date
	i any was specialist (	Title)
	(Code 83)- MARCORSYSCOM, Albany, GA	<u> </u>
Change Approved by	Logistics Management Specialist	Name) /5_04_0 _Date
	(Code (Annual Code (Code	
Change Disapproved	by Logistics Management Specialist	(Name)Date
	(Code_MARCORSYSCOM, Albany, GA	)